2018/11/7

© Goods Master 2018-2019 List of Errors

The following clerical errors were found in Good Master 2018-2019 published in September, 2018. Please correct these errors of your Goods Master.

| Page Cont | ents | (Wrong) | (Correct) | Remarks |
|--|---|------------------|---------------------|--|
| | | | | |
| 76 Description of Premium Suction Technology | | SUPER AIR FILTER | SUPER HYBRID FILTER | ※Preimum Suction Kit includes Super Hybrid Filter. |
| 88 Code No. of Super Air Filter for Toyota Passo (KGC30/35,KGC10/15) | | 70017-AT118 | - | 70017-AT118 does not exist. |
| 169 Code No. of Gasket Turbine Outlet Pipe o | of GTIII Turbine Option Part for GTIII-RS | 1409-RA065 | 1499-RA065 | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |